


No. 531 間取図


外観



1 F



2 F



天井の雨漏り痕を確認。現状引渡。
令和5年に屋根は修繕済み。

①



②



③



④



⑤



⑥



⑦



⑧



⑨



⑩



⑪



⑫



⑬



⑭



⑮



⑯



床のたわみを確認。現状引渡。